

- 2. ON BASIS OF UNSATISFACTORY RESULTS ON REPEAT OF YESTERDAYS POSITIVE TESTS, AND AFTER DISCUSSIONS WITH IDEN IT IS BELIEVED BEST TO PROCEED FOR TIME BEING USING SODIUM THIOSULFATE CRYSTALS, BORROWED POWDER HARDENER AND ACETIC ACID, ALTHOUGH RESULTS WITH THIS METHOD NOT UP TO YESTERDAYS STANDARDS.
 - 3. LACK OF CONSISTENCY IN REPEAT TESTS CAN NOT BE EXPLAINED AT THIS TIME.
 - 4. LENGTH OF TIME STILL PROBLEM. PLEASE ADVISE SOONEST.

 END OF MESSAGE